	FOOD AND DRUG ADMINISTRATION	COPY	
DISTRICT OFFICE ADDRESS AND PHONE NUMBER		DATE(S) OF INSPECTION	
6th & Kipling St. (P.O. Box 25087) Denver, CO 80225-0087 303-236-3000 Fax: 303-236-3100		09/20,21,22,23,24 & 27,28,29/2021	
		FEINUMBER	
		3015144909	
Industry Information: www.fda.gov/oc/industry		3013144909	
JAME AND TITLE OF INDIVIDUAL TO WHOM REPORT IS ISSUE			
ro: Mr. Joseph W. Bagan, Chief Executive Office			
	STREET ADDRESS		
STAQ Pharma, Inc.	And approximation provide the second second second	14135 E 42nd Avenue, Suite 50	
STATE AND ZIP CODE		TYPE OF ESTABLISHMENT INSPECTED	
Denver, CO 80239-5214	Outsourcing Facilit	y	
DESERVATIONS; AND DO NOT REPRESENT A FINAL AGENC DESERVATION, OR HAVE IMPLEMENTED, OR PLAN TO IM DEJECTION OR ACTION WITH THE FDA REPRESENTATIVE(S YOU HAVE ANY QUESTIONS, PLEASE CONTACT FDA AT THE DURING AN INSPECTION OF YOUR FIRM (I) (WE) OBSERVED:	PLEMENT CORRECTIVE ACTION IN RESPO 5) DURING THE INSPECTION OR SUBMIT TH PHONE NUMBER AND ADDRESS ABOVE.	ONSE TO AN OBSERVATION, YOU MAY DISCUSS TH	
Observation 1			
Procedures designed to prevent microbiological include adequate validation of the aseptic p		ducts purporting to be sterile did not	
Specifically,			
	(b)(4) and $(b)(7)$ (b) (4)	Poom (b)(4) after the I EH was moved	
A) The firm failed to recertify the ISO 5 LF from the (b) (4) to the(b) (4) of the I has been producing aseptically filled (b) (4 LFH: ^{(b) (4)} located on the (b) (4) of (b) B) The Nonviable (b) (4) and (b) (4)	SO 7 room during the Smoke S)) syringes from 09/17/ (4) Room ^{(b) (4)} . Viable air samplers inside the I	2020 to the present with the ISO 5	
A) The firm failed to recertify the ISO 5 LF from the (b) (4) to the(b) (4) of the I has been producing aseptically filled (b) (4 LFH- $^{(b)}$ (4) located on the (b) (4) of (b) B) The Nonviable (b) (4) and (b) (4) while conducting the Dynamic Smoke Stud	SO 7 room during the Smoke S)) syringes from 09/17/ (4) Room ^{(b) (4)} . Viable air samplers inside the I	tudy conducted on 09/17/2020. The fir 2020 to the present with the ISO 5	
A) The firm failed to recertify the ISO 5 LF from the (b) (4) to the(b) (4) of the I has been producing aseptically filled (b) (4 LFH. ^{(b) (4)} located on the (b) (4) of (b) B) The Nonviable (b) (4) and (b) (4) while conducting the Dynamic Smoke Stud Observation 2	SO 7 room during the Smoke S)) syringes from 09/17/ (4) Room ^{(b) (4)} . Viable air samplers inside the I ly on 09/17/2020.	tudy conducted on 09/17/2020. The fir 2020 to the present with the ISO 5 SO 5 LFH. ^{(b) (4)} were not in operation	
A) The firm failed to recertify the ISO 5 LF from the (b) (4) to the(b) (4) of the I has been producing aseptically filled (b) (4 LFH. ^{(b) (4)} located on the (b) (4) of (b) B) The Nonviable (b) (4) and (b) (4) while conducting the Dynamic Smoke Stud Observation 2 Aseptic processing areas are deficient regan Specifically,	SO 7 room during the Smoke S)) syringes from 09/17/ (4) Room ^{(b) (4)} . Viable air samplers inside the I ly on 09/17/2020.	tudy conducted on 09/17/2020. The firm 2020 to the present with the ISO 5 SO 5 LFH. ^{(b) (4)} were not in operation	
A) The firm failed to recertify the ISO 5 LF from the (b) (4) to the(b) (4) of the I has been producing aseptically filled (b) (4 LFH: ^{(b) (4)} located on the (b) (4) of (b) B) The Nonviable (b) (4) and (b) (4) while conducting the Dynamic Smoke Stud Observation 2 Aseptic processing areas are deficient regar	SO 7 room during the Smoke S)) syringes from 09/17/ (4) Room ^{(b) (4)} . Viable air samplers inside the I ly on 09/17/2020. rding the system for monitoring uding but not limited to, the fol	tudy conducted on 09/17/2020. The fir 2020 to the present with the ISO 5 SO 5 LFH. ^{(b) (4)} were not in operation environmental conditions.	
A) The firm failed to recertify the ISO 5 LF from the (b) (4) to the(b) (4) of the I has been producing aseptically filled (b) (4 LFH. ^{(b) (4)} located on the (b) (4) of (b) 3) The Nonviable (b) (4) and (b) (4) while conducting the Dynamic Smoke Stud Observation 2 Aseptic processing areas are deficient regar Specifically, There is no environmental monitoring, incl	SO 7 room during the Smoke S)) syringes from 09/17/ (4) Room ^{(b) (4)} . Viable air samplers inside the I ly on 09/17/2020. rding the system for monitoring uding but not limited to, the fol	tudy conducted on 09/17/2020. The firm 2020 to the present with the ISO 5 SO 5 LFH. ^{(b) (4)} were not in operation environmental conditions.	
A) The firm failed to recertify the ISO 5 LF from the (b) (4) to the(b) (4) of the I has been producing aseptically filled (b) (4 LFH. ^{(b) (4)} located on the (b) (4) of (b) 3) The Nonviable (b) (4) and (b) (4) while conducting the Dynamic Smoke Stud Observation 2 Aseptic processing areas are deficient regar Specifically, There is no environmental monitoring, incl nside the ISO 5 Laminar Flow Hood (LFH	SO 7 room during the Smoke S)) syringes from 09/17/ (4) Room ^{(b) (4)} . Viable air samplers inside the I ly on 09/17/2020. rding the system for monitoring uding but not limited to, the fol [. ^{(b) (4)}), which is located in (t	tudy conducted on 09/17/2020. The fir 2020 to the present with the ISO 5 SO 5 LFH. ^{(b) (4)} were not in operation environmental conditions. lowing ancillary equipment located b) (4) Room ^{(b) (4)} : Add Continuation Page	
A) The firm failed to recertify the ISO 5 LF from the (b) (4) to the(b) (4) of the I has been producing aseptically filled (b) (4 LFH. ^{(b) (4)} located on the (b) (4) of (b) 3) The Nonviable (b) (4) and (b) (4) while conducting the Dynamic Smoke Stud Observation 2 Aseptic processing areas are deficient regar Specifically, There is no environmental monitoring, incl nside the ISO 5 Laminar Flow Hood (LFH	SO 7 room during the Smoke S)) syringes from 09/17/ (4) Room ^{(b) (4)} . Viable air samplers inside the I ly on 09/17/2020. rding the system for monitoring uding but not limited to, the fol [. ^{(b) (4)}), which is located in (t	tudy conducted on 09/17/2020. The fir 2020 to the present with the ISO 5 SO 5 LFH. ^{(b)(4)} were not in operation environmental conditions. lowing ancillary equipment located (a) (4) Room ^{(b) (4)} : Add Continuation Page ITLE (Print or Type) DATE ISSUED	
A) The firm failed to recertify the ISO 5 LF from the (b) (4) to the(b) (4) of the I has been producing aseptically filled (b) (4 LFH- ^{(b)(4)} located on the (b) (4) of (b) 3) The Nonviable (b) (4) and (b) (4) while conducting the Dynamic Smoke Stud Observation 2 Aseptic processing areas are deficient regar Specifically, There is no environmental monitoring, incl nside the ISO 5 Laminar Flow Hood (LFH	SO 7 room during the Smoke S)) syringes from 09/17/ (4) Room ^{(b) (4)} . Viable air samplers inside the I ly on 09/17/2020. rding the system for monitoring uding but not limited to, the fol [. ^{(b) (4)}), which is located in (t	tudy conducted on 09/17/2020. The fir 2020 to the present with the ISO 5 SO 5 LFH. ^{(b)(4)} were not in operation environmental conditions. lowing ancillary equipment located o) (4) Room ^{(b)(4)} : Add Continuation Page ITLE (Print or Type) DATE ISSUED	
A) The firm failed to recertify the ISO 5 LF from the (b) (4) to the(b) (4) of the I has been producing aseptically filled (b) (4 LFH- ^{(b) (4)} located on the (b) (4) of (b) 3) The Nonviable (b) (4) and (b) (4) while conducting the Dynamic Smoke Stud Observation 2 Aseptic processing areas are deficient regan Specifically, There is no environmental monitoring, incl nside the ISO 5 Laminar Flow Hood (LFH EMPLOYEE(S) SIGNATURE SEE REVERSE	SO 7 room during the Smoke S)) syringes from 09/17/ (4) Room ^{(b) (4)} . Viable air samplers inside the I ly on 09/17/2020. rding the system for monitoring uding but not limited to, the fol [. ^{(b) (4)}), which is located in (t	tudy conducted on 09/17/2020. The fir 2020 to the present with the ISO 5 SO 5 LFH. ^{(b)(4)} were not in operation environmental conditions. lowing ancillary equipment located (a) (4) Room ^{(b)(4)} : Add Continuation Page ITLE (Print or Type) DATE ISSUED gator 09/29/2021	

	DEFAN	TMENT OF HEALTH AND HUMAN SER FOOD AND DRUG ADMINISTRATION	VICES	
DISTRICT OFFICE M			DATE(S) OF INSPECTION	
DISTRICT OFFICE ADDRESS AND PHONE NUMBER				
6th & Kipling St. (P.O. Box 25087) Denver, CO 80225-0087 303-236-3000 Fax: 303-236-3100 Industry Information: www.fda.gov/oc/industry		09/20,21,22,23,24 & 27,28,29/2021		
		FEINUMBER		
		3015144909		
AME AND TITLE OF	INDIVIDUAL TO WHOM REPORT IS ISSUE	ED		
O: Mr. Joseph	W. Bagan, Chief Executive Office	r		
IRM NAME	STREET ADDRESS			
STAQ Pharma, I		14135 E 42nd Av		
	TE AND ZIP CODE TYPE OF ESTABLISH			
Denver, CO 802	39-5214	Outsourcing Facil	ility	
A) Non-viable B) Power cord)) hoses feeding into the I located in ISO 7 (b) (4)		
Electrical Out	let (inside the LFH)			
	screw caps of the (b) (4)			
	g Bar and IV hooks			
E) (b) (4)) L shaped bar that supports	s the Fill Bag (Fill Bag stand)		
Observation 3				
Specifically, th	he following products were co	tion 503B(b)(2)(A) of the FDa		
	duct Report:	ompounded and not identified	on your report dated in:	
Buffered Lid	duct Report: locaine 10 mg/mL in Acetate 1.5 mg/mL Nasal S		on your report dated in:	
 Buffered Lid Desmopressi 	locaine 10 mg/mL		on your report dated in:	
Buffered Lid Desmopressi December 202 Phenylephrir	locaine 10 mg/mL in Acetate 1.5 mg/mL Nasal S		on your report dated in:	
Buffered Lid Desmopressi December 202 Phenylephrir	locaine 10 mg/mL in Acetate 1.5 mg/mL Nasal S 20 Product Report: ne 100 mcg/mL		on your report dated in:	
Buffered Lid Desmopressi December 202 Phenylephrir	locaine 10 mg/mL in Acetate 1.5 mg/mL Nasal S 20 Product Report: ne 100 mcg/mL		on your report dated in:	
Buffered Lid Desmopressi December 202 Phenylephrir	locaine 10 mg/mL in Acetate 1.5 mg/mL Nasal S 20 Product Report: ne 100 mcg/mL		on your report dated in:	
Buffered Lid Desmopressi December 202 Phenylephrir	locaine 10 mg/mL in Acetate 1.5 mg/mL Nasal S 20 Product Report: ne 100 mcg/mL		on your report dated in:	
Buffered Lid Desmopressi December 202 Phenylephrir	locaine 10 mg/mL in Acetate 1.5 mg/mL Nasal S 20 Product Report: ne 100 mcg/mL		on your report dated in:	
Buffered Lid Desmopressi December 202 Phenylephrir	locaine 10 mg/mL in Acetate 1.5 mg/mL Nasal S 20 Product Report: ne 100 mcg/mL			
Buffered Lid Desmopressi December 202 Phenylephrir Ropivacaine	locaine 10 mg/mL in Acetate 1.5 mg/mL Nasal S 20 Product Report: ne 100 mcg/mL HCl 2 mg/mL		Add Continuation Page	
 Buffered Lid Desmopressi December 202 Phenylephrir Ropivacaine 	locaine 10 mg/mL in Acetate 1.5 mg/mL Nasal S 20 Product Report: ne 100 mcg/mL	Spray EMPLOYEE(S) NAME AND	Add Continuation Page	
Buffered Lid Desmopressi December 202 Phenylephrir Ropivacaine	locaine 10 mg/mL in Acetate 1.5 mg/mL Nasal S 20 Product Report: ne 100 mcg/mL HCl 2 mg/mL	Spray	Add Continuation Page TITLE (Print or Type) DATE ISSUED tigator 09/29/2021	

The observations of objectionable conditions and practices listed on the front of this form are reported:

1. Pursuant to Section 704(b) of the Federal Food, Drug and Cosmetic Act, or

 To assist firms inspected in complying with the Acts and regulations enforced by the Food and Drug Administration.

Section 704(b) of the Federal Food, Drug, and Cosmetic Act (21 USC 374(b)) provides:

"Upon completion of any such inspection of a factory, warehouse, consulting laboratory, or other establishment, and prior to leaving the premises, the officer or employee making the inspection shall give to the owner, operator, or agent in charge a report in writing setting forth any conditions or practices observed by him which, in his judgement, indicate that any food, drug, device, or cosmetic in such establishment (1) consists in whole or in part of any filthy, putrid, or decomposed substance, or (2) has been prepared, packed, or held under insanitary conditions whereby it may have become contaminated with filth, or whereby it may have been rendered injurious to health. A copy of such report shall be sent promptly to the Secretary."

457DA 9/25/2021 JAG 2553