

**DEPARTMENT OF HEALTH AND HUMAN SERVICES
FOOD AND DRUG ADMINISTRATION**

| | |
|--|--------------------------|
| DISTRICT ADDRESS AND PHONE NUMBER | DATE(S) OF INSPECTION |
| 158-15 Liberty Ave. Jamaica, NY 11433 (718) 340-7000 Fax: (718) 662-5661 Industry Information: www.fda.gov/oc/industry | 06/01/2009 - 07/06/2009* |
| | FEI NUMBER |
| | 2427372 |

| |
|--|
| NAME AND TITLE OF INDIVIDUAL TO WHOM REPORT ISSUED |
| TO: John M. Graham, QA Manager |

| | |
|------------------------------------|------------------------|
| FIRM NAME | STREET ADDRESS |
| Trans-Packers Services Corporation | 419 Vandervoort Avenue |

| | |
|--------------------------------|------------------------------|
| CITY, STATE, ZIP CODE, COUNTRY | TYPE ESTABLISHMENT INSPECTED |
| Brooklyn, NY 11222-5313 | Manufacturer |

This document lists observations made by the FDA representative(s) during the inspection of your facility. They are inspectional observations, and do not represent a final Agency determination regarding your compliance. If you have an objection regarding an observation, or have implemented, or plan to implement, corrective action in response to an observation, you may discuss the objection or action with the FDA representative(s) during the inspection or submit this information to FDA at the address above. If you have any questions, please contact FDA at the phone number and address above.

DURING AN INSPECTION OF YOUR FIRM WE OBSERVED:

OBSERVATION 1

Failure to maintain buildings in repair sufficient to prevent food from becoming adulterated.

Specifically, during the course of the inspection two production rooms were noted to have peeling paint on the ceilings as follows;

- On 06/01/09, while in Mixing room (b) (4), I observed peeling paint on the ceiling above the mezzanine area. The peeling paint was in close proximity to the bag dump station and the (b) (4) blender. This could possibly result in the finished product (including all Dairy Shakes) being contaminated with paint chips.
- On 06/09/09, while in the mezzanine of the Bodolay Packaging room, I observed peeling paint on the ceiling. The peeling paint was in close proximity to the stainless steel hopper that feeds bulk material to the Bodolay packaging machine directly below. This could possibly result in the finished product (including all Dairy Shakes) being contaminated with paint chips.

*** DATES OF INSPECTION:**

06/01/2009(Mon), 06/02/2009(Tue), 06/03/2009(Wed), 06/04/2009(Thu), 06/05/2009(Fri), 06/09/2009(Tue), 06/11/2009(Thu), 06/19/2009(Fri), 07/06/2009(Mon)

| | | |
|---------------------------------|---|-------------|
| SEE REVERSE OF THIS PAGE | EMPLOYEE(S) SIGNATURE | DATE ISSUED |
| | Frank Verni, Investigator Meredith P. Soehl, Investigator Sarah A. Wangseng, Investigator | 07/06/2009 |