

## Local Posting: NCTR-2024-123541 Repair of Xevo TQ-S Mass Spectrometer

5/28/2024

The FDA has a requirement for repair service to a Waters Xevo TQ-S Mass Spectrometer. The repair service is required to accomplish the following: 1) Replace Dual Quad PCB Assembly; and 2) Ensure that the Xevo TQ-S system is working at optimal capacity.

For more information regarding this requirement please contact Warren Dutter at 870-543-7577 or email at [warren.dutter@fda.hhs.gov](mailto:warren.dutter@fda.hhs.gov). All applicable FAR and HHSAR Clauses will be included in any resultant award.

All responsible sources may submit a response which, if timely received, must be considered by the agency. Responses due by 1:00 PM Central Time on 5/31/2024.

Services to be performed at NCTR, 3900 NCTR Road, Jefferson, AR 72079.