DEPARTMENT OF HEALTH AND HUMAN SERVICES FOOD AND DRUG ADMINISTRATION				
district address and phone number 19701 Fairchild			DATE(S) OF INSPECTION	
	ne, CA 92612-2445		3/20/2017-3/24/2017 FEINUMBER	
(949)608-2900 Fax: (949)608-4417			3011630209	
NAME AND TITLE OF INDIVIDUAL TO WHOM REPORT ISSUED				
William A. Stuart, RPh , President				
FIRM NAME	tuait, Kiii , liesiuent	STREET ADDRESS	THE RESIDENCE OF THE PARTY OF T	
Hartley Medical Center Pharmacy, 113 W V		113 W Vi	ictoria St	
Incorporated			MENT INSPECTED	
	2. No. 4 (2015) 2. Co.		r of Sterile Drug Products	
Long Beach, C	Peach, CA 50003-2102 Floates of Beelife Blag floates			
This document lists observations made by the FDA representative(s) during the inspection of your facility. They are inspectional observations, and do not represent a final Agency determination regarding your compliance. If you have an objection regarding an observation, or have implemented, or plan to implement, corrective action in response to an observation, you may discuss the objection or action with the FDA representative(s) during the inspection or submit this information to FDA at the address above. If you have any questions, please contact FDA at the phone number and address above.				
DUBING AN INCREATION OF YOUR FIRM LODGERIVED.				
Observation 1) Equipment, materials, and/or supplies are not disinfected prior to entering the aseptic				
processing areas	5.			
10 20 20 20 20 20				
Specifically,				
57 57				
The repeater pump used to dispense drug stocks into smaller unit vials is wheeled from the ISO-7 Ante room to the ISO-6 IV Clean Room when needed and wheeled back to the Ante room when not needed.				
Ol (2) The ISO 1 (C 1				
Observation 2) The ISO-classified areas have difficult to clean, particle-generating, or visibly dirty				
equipment or su	irfaces.		K. W	
Specifically,			8	
F ,				
I observed that gaps in the emergency exit double doors from the ISO-6 IV room are sealed with tape, but there were some areas where the tape had been worn or was not fully maintaining the seal, thus possibly compromising the integrity of the ISO-6 room.				
				27
5				\$8
	84	裁		
	T		100.4	Spin-
SEE REVERSE OF THIS PAGE	Roger F Zabinski, Investiga	tor	X Roger F Zabinski Roger F Zabinski Irrestostor	DATE ISSUED 3/24/2017